

55 Line

Glasurit Color Adjustment Chart

glasurit.com



A brand of
BASF – We create chemistry

Solid Colors




	T. Base : M 99/19 80 : 20	T. Base : M 99/19 20 : 80	T. Base : M 99/19 80 : 20	T. Base : M 99/19 20 : 80
A 097				
M 25			A 353	
A 125			A 372	
M 105			A 423	
A 136			A 430	
A 137			A 532	
M 141			A 548	
A 143			A 556	
M 146			A 589	
A 150			A 590	
M 177			A 640	
M 201			A 697	
A 335			A 927	
M 306			A 929	
A 307			A 974	
A 324				
A 347				
3A0				
A 350				

Effect Colors

	T. Base 100	T. Base : ● 80 : 20	T. Base 100	T. Base : ● 80 : 20
M 010			A 640	
M 179			A 929	
M 319			A 347	
M 505			A 929	
M 506			A 929	
M 800			A 347	
M 802			A 347	
M 919			A 640	
M 930			M 99/19	
E 014			A 640	
E 025			A 929 95 : 5	
E 120			A 929	
E 220			A 929	
E 330			A 929	
E 435			A 929	
E 440			A 929	
E 460			A 929	
E 480			A 347	
E 520			A 929	

Metallic Colors

	T. Base 100	T. Base : A 640 80 : 20
M 99/09		
M 99/10		
M 99/12		
M 99/17		
M 99/19		
M 99/20		
M 99/21		
M 99/22		
E 280		
E 920		



	more violet	bluer	greener	yellower	more orange	redder	darker
		A532 A589	A532 A589			A352 A353	A423 A430 A430
	A423 A353	A532 A548 A548 A556	A697 A640	A640 A136 A143 A143 M177	M105 M146 A372 M201	A347 M306 A350 A352 A352	A929 A929 A974 A974
	A423 A430	A548 A548 A556	A697 A640	A136 M105 A143 M177	M105 M146 A372 M201	A347 M306 A350 A352	A548 A548 A589 A556
			A697 A640		A372 M201	M306 A136 A324 A143	A143
				A136 M105 A143	M105 M146 A372 M201	A347 A324 A324 A929	M201 M306 A974 A974
				A136 M105 A143 A335	M105 M146 A372 M201	A347 A324 A324 A929	A929 A974 A974
	A430 A353 A430			A136 M105 A143 A335	M105 M146 A372 M201	A347 A324 A324 A929	A347 A347 A352 A352

* Please use the bases from the corresponding mixing formula.